

ANNOUNCEMENT OF BLFC CHANGE ON RUNXIN VALVE F68P - "Y" TYPE

Dear Customer,

we inform you that Runxin manufacturer proceeded to modify injector-BLFC coupling for YELLOW injector configuration.

So, starting from next delivery following valves:

RF68P3Y

will be supplied with YELLOW injector mounted (as usual) but with BLUE DLFC #8468055 .



NEW COUPLING

The cause of such modification was to shorten the brine filling time and at the same time save some water going to the drain (during brine filling).

As blue BLFC #8468055 has flow rate 5,6 l/min , we recommend you to calculate the refill time accordingly.

Runxin manufacturer confirmed all valves that were delivered since implementation of the change are working properly and they do not require modification / change of the installed BLFC.

Our Technical Dept. remain at your disposal in case of need.

Best regards.

Settimo Milanese, October 26th 2020