

ANNOUNCEMENT OF BLFC CHANGE ON RUNXIN VALVES F69P - "Y" TYPE

Dear Customer,

we inform you that Runxin manufacturer proceeded to modify injector-BLFC coupling for valve whom in subject with PINK injector configuration.

So starting from next delivery following valves:

RF69P1Y - RF69P3Y - RF69P3Y/F70BL

will be supplied with PINK injector mounted (as usual) but with BLUE DLFC #8468055 instead of BLACK BLFC # 8468057.



ORIGINAL COUPLING

NEW COUPLING

The cause of such modification was to shorten the brine filling time and at the same time save some water going to the drain (during brine filling).

As blue BLFC #8468055 has flow rate about 7 times more than black BLFC #8468057 (5,6 l/min against 0,83) we recommend to scale back refill time accordingly.

However additionally to new configuration indicated above black BLFC will be supplied too.

Runxin manufacturer confirmed all valves that were delivered since implementation of the change are working properly and they do not require modification / change of installed BLFC ("..057").

Our Technical Dept. remain at your disposal in case of need.

Best regards.

Settimo Milanese, October 26th 2020